

# Data Interface
## Fits Fiat 500 2012–2015

### INTERFACE FEATURES

- Designed for non-amplified and amplified systems
- Provides accessory power (12-volt 10-amp)
- Retains R.A.P. (Retained Accessory Power)
- Provides NAV outputs (parking brake, reverse, speed sense)
- Pre-wired for Axxess SWC interface (sold separately)
- Retains factory 3.5mm AUX-IN & OE Bluetooth® connectivity
- High-level speaker input
- Micro "B" USB updatable

### INTERFACE COMPONENTS

- AXDI-6515 Interface
- LD-AX-XSVI-FT1 Harness

**Product Info**

### TABLE OF CONTENTS

Connections LD-AX-XSVI-FT1.....2
Installation .....3
Programming.....3

### TOOLS & INSTALLATION ACCESSORIES REQUIRED


- Crimping tool and connectors, or solder gun, solder, and heat shrink • Tape • Wire cutter
- Zip ties • Multimeter

Visit AxxessInterfaces.com
for more detailed information about the product and up-to-date vehicle specific applications

***ATTENTION:** With the key out of the ignition, disconnect the negative battery terminal before installing this product. Ensure that all installation connections, especially the air bag indicator lights, are plugged in before reconnecting the battery or cycling the ignition to test this product.*
***NOTE:** Refer also to the instructions included with the aftermarket radio.*


© COPYRIGHT 2025 METRA ELECTRONICS CORPORATION

# CONNECTIONS: LD-AX-XSVI-FT1



## INSTALLATION

**With the key in the off position:**

- Connect the **AXDI-6515 harness** to **AXDI-6515 interface**, and then to the wiring harness in the vehicle.

  **Note:** If using the Axxess SWC interface, connect it after you program and test the AXDI-6515, with the key in the off position.

## PROGRAMMING

**Attention!** If the interface loses power for any reason, the following steps will need to be performed again.

- Turn the key (or push-to-start button) to the ignition position and wait until the radio comes on.

  **Note:** If the radio does not come on within 60 seconds, turn the key to the off position, disconnect the interface, check all connections, reconnect the interface, and then try again.

- Turn the key to the off position, and then to the accessory position. Test the interface/radio for proper operation.

Having difficulties? We're here to help.

Contact our Tech Support line at:
**386-257-1187**

Or via email at:
techsupport@metra-autosound.com

**Tech Support Hours (Eastern Standard Time)**

Monday - Friday: 9:00 AM - 7:00 PM
Saturday: 10:00 AM - 5:00 PM
Sunday: 10:00 AM - 4:00 PM

**Metra recommends MECP certified technicians**


© COPYRIGHT 2025 METRA ELECTRONICS CORPORATION