

OPTIMAL TEMPERATURES

	WARMING	BAKING	ROASTING
	200°-275°	300°-375°	375°-550°

Hang or stand thermometer in the oven during cooking to assure that roasted or baked items are cooked evenly. An oven thermometer will help pin point hot spots or oven temperature calibration issues ensuring better results.