


ASSEMBLY INSTRUCTION


Saldana Corner PC

Components




A
x1

Assembly Instructions




| Hardware List | | | | |
|---------------|--|----------------|----------|---|
| a | | Plastic Leg | Ø60x43mm | 5 |
| b | | Plastic Washer | Ø8 | 5 |




ASSEMBLY INSTRUCTION

Saldana Corner PC


Assembly of the sectionals



The prong and the connector must be aligned well.



How to disconnect



Lift up the right sectional and pull it out .

